





Exterior Before




Exterior Spring 2017



Entranceway & Bathrooms Before




Entranceway & Bathrooms Spring 2017



Wheel Room Before



Wheel Room Spring 2017



Sink Room Before



Sink Room Spring 2017: Sink fabricated by Mario Velardo



Interior was re-built from the studs (picture taken from entryway)



Art Room Spring 2017

Art Room Spring 2017


Green Room Spring 2017

Theater Room Before

The basic structure has remained largely the same









During heavy rainstorms, the building and surrounding parking lot would flood, necessitating extensive drainage work to sustain Cedar Lane Park and the building

Flooding in adjacent parking lot

Drainage work being completed in parking lot








Drainage work along pond and road entering Cedar Lane Park






Drainage work along pond and road entering Cedar Lane Park

Finishing touches on sidewalks around the Cedar Lane Arts Center Kilns will be stored in the Ice House across the driveway, but the entry to the building and floor inside was several steps off the ground





Ice House floor before being lowered to ground level



Ice House floor being lowered to ground level









A window on the Ice House had been broken, and needed to be repaired


The window, with new wiring, was repaired by Parks Foreman Mario Velardo






Ice House exterior and interior after lowering floors and exterior repairs





The entry road was widened to accommodate two-way traffic and more visitors to the park





Finished entry and signs directing visitors to the latest addition to Cedar Lane Park!



